

Suspect asbestos containing material (damaged) observed around heat duct in basement.



Suspect asbestos containing material (damaged) observed in the dirt basement floor.

Tar patched shingles observed.



Improperly installed roof shingles observed (exposed shingle nails also observed.)



At least one shingle nail on the back side of the roof has worked its way up through an asphalt shingle.

Lack of a cricket at chimney. Flashing was tar covered.

